


Bona Belt Previous Models AMO110018.3 Belt Motor



Bona Belt Previous Models AMO110018.3 Belt Motor

.	ASO115825.3	Motor cap.box 1-3 phase Poly-V
.	ASO903790	El. box with transformer cpl.
045 .	ASO115245	Motor pulley Poly-V
047 .	ASO115147.3	Cap.box cover grey
048 .	ASO115144.3	Base plate
050 .	ASO900130	El.motor 3 KW 220/380V ABM
051 .	ASO115051	Hinge for motor
052 .	ASO115153	Tensioner screw
053 .	ASO945148	Leaded link GN343.1 25-M8 KR
054 .	ASO945144	Locking knob WN730 T40-M8x20
063 .	ASO115163	Intermediate plate
064 .	ASO115164	Front motor bracket
069 .	ASO115169	Mounting plate
083 .	ASO945132	Lifting handle motor
104 .	ASO924260	Poly-V-belt 260 J5, ventilator
106 .	ASO951518	Screw M6S M8x20 fzb
107 .	ASO965003	Washer 8,2 X 26 X 5 fzb
116 .	ASO924328	Poly-V-belt 328 drum
130 .	ASO960900	Nut M6M M16 fzb
132 .	ASO952515	Screw MC6S M8x14 fzb
133 .	ASO952420	Screw MC6S M6x30 fzb
135 .	ASO965003	Washer 8,2 X 26 X 5 fzb
136 .	ASO951519	Screw M6S M8x25 fzb
137 .	ASO952416	Screw MC6S M6x16 fzb

138 .	ASO903426	Motor inlet 5 pol red
139 .	ASO903772	Switch 800 E Heavy duty
141 .	ASO115170	Rubber sealing
142 .	ASO115172	Rubber sealing motor base plat
143 .	ASO952416	Screw MC6S M6x16 fzb
144 .	ASO968002	Spacer DB 6x12,5x0,2
145 .	ASO958121	Screw MRX M5x35 fzb Philips
149 .	ASO932820	Key 8x7x20
150 .	ASO903750	Contactor 5,5 kW 100-M12N
152a .	ASO903765	Circuit card 1/3 and 1-phase
152b .	ASO903785	Circuit card 1/3 1ph.w/o.capa
154 .	ASO903102	Start condensator 100 uF
156 .	ASO903140	Condensator cont.use 140 uF